
# **SD5 5 Channels Universal Monitoring Indicator**

The Vertex SD5 is our new 5 channel Digital Display Indicator. It is a low cost, yet reliable, Digital Panel Indicator. You can set the scan rate between 0~10 seconds per channel or stop on one channel if required. You can also disable the channels you are not using. The SD5 comes standard with two alarms that cover all 5 inputs. RS485 comms are also available as an optional extra so that these indicators can be networked.

### 1. Front Panel and Keypad description:




display/ ir	ndicator	indication	Description	
Display	PV	<i>8.8.8.8.</i>	Shows the process values PV1~PV5     Also displays the parameter name when selected.	
Display	sv	8.8.8.	Tells you which channel is being displayed in PV display above CH-1~CH-5     Also displays the parameter data/set value when selected.	
Indicator	Alarm	AL1、AL2(A1、A2)(AL、AH)	Alarm indicators. The alarm indicators will blink if you have selected the time function while timer alarm is counting time.	
Indicator	TX RX	TX / RX	When the TX and RX indicators are blinking respectively it indicates that the communication function is working.	


Keypad	Description	
SET	Press once to access the next programmable parameter. Press this key for 5 seconds to reset alarm timer/ LATH RESET	
	Press to increase the set value or parameter value. Press to access the last channel process value PV(scan manually)	
V	Press to decrease the set value or parameter value./ Press to access the next channel process value PV(scan manually)	
◂	Shift Key	
SET+ Press once together	Return to normal position	
SET+ Press together for 5 seconds	Press the SET+ keys together for 5 seconds to select programming level, then press SET key to enter this level.	


#### 2. Initial Setup Requirements

- 2.1. Connect mains power to T23 and T24
- 2.2. Access the parameters by pressing the **SET+** keys together for 5 seconds.
- 2.3. Set the input type you will be using (it must be the same on all channels and all probes need to be the same type and use the same range.)
- 2.4. Then set the number of channels you will be using and the scan time (between 0 ~ 10 seconds) for which each input must be displayed as the scan rotates.
- 2.5. Check that the "unit" is deg C, select your decimal point preference,
- 2.6. Set the LoLt to the zero value for your measuring range. (This is not a limit as such but the low value of the measuring range and should not be set above zero)
- 2.7. Set the HiLt to the high value of your measuring range, typically 0~100 or 0~200 etc
- 2.8. The balance of these parameters are used for either alarm or RS485 comms setup and will be covered elsewhere.
- 2.9. Connect inputs to the appropriate input terminals. ie: Thermocouple on Ch1 using T10 (-ve) and T11 (+ve) or if using PT100's using T10 + T11 + T12 and so on having up to 5 inputs.
- 2.10. Now turn the power on and the unit should work as desired.
- 2.11. Note by setting the scan time to zero, you will be able to page through the different channels manually using either the up or down button.


#### 3. Wiring Diagram:







- 1. Before wiring, check the controller label for correct model number and options.
- 2. Mains power can be ac or dc between 90 and 264 volts and always goes on T23 and T24
- 3. Terminals T20, T21 and T22 are used for the alarms.
- 4. Terminals T16 and T17 are used for the RS485 comms.
- 5. For thermocouple input, use the appropriate compensation wire. And note the polarity of the input signal wiring
- 6. To avoid noise induction, keep input signal wires away from power lines.
- 7. Prepare the panel cutout with proper dimensions (92 + 0.5 and 45 + 0.5 mm)



### 4. Table 1 Input type and range

TYPE	Code	RANGE( □□)		RANGE( PF)	
J		-50~1000	-50.0~999.9	-58~1832	-58.0~999.9
K	Ľ	-50~1370	-50.0~999.9	-58~2498	-58.0~999.9
Т	L	-270~400	-199.9~400.0	-454~752	-199.9~752.0
DPT	d-PE	-200~600	-199.9~600.0	-328~1112	-199.9~999.9
LINE	LinE	N/A			

## 5. Specifications

	Specifications				
Innut	Inputs are configurable between Type J, Type K and Type T				
Input	RTD: DIN PT-100				
Ranges	All 5 channels need to be the same input and range. See ranges listed below.				
Displays	The top display shows the reading and the bottom indicates which channel it is				
2.00.000	for.				
Accuracy	T/C±1°C; RTD ±0.2°C				
Sampling Time	0.25 second				
	The indicator comes standard with 2 configurable alarms. These alarms work				
Alarm	across all 5 input channels and will be activated if any one channel exceeds				
	the set value. Rated at 10A/ 240 VAC (Resistive load)				
	Rated Voltage: AC 90~264VAC 50 / 60Hz				
	Ambient Temperature: 0~50°C				
General	IP Rating: IP 65				
	Ambient Humidity: 0~90 % (Non-Condensing)				
	Consumption: Less than 3VA				


### 6. PARAMETER LOCK

The parameter lock can be used to restrict unwanted access to the settings in your indicator

0001	Only LOCK is adjustable.
0010	Only LOCK and first level are adjustable.
0011	Second level is adjustable.
0100	All parameters are adjustable.

The "First level" starts with "A1S1" and the second level starts with "type"

### 7. Parameters Flowchart:



# 8. Parameter Description:

Param eter	Code	Description		Range	Default
PV	Х	Process value PV1~PV5		X	Х
CH-1	EH- I	on.	blinking while alarm relay is		
CH-2	CH-2	on.	blinking while alarm relay is		
CH-3	EH-3	on.	blinking while alarm relay is	Х	Χ
CH-4	Ен-ч	on.	blinking while alarm relay is		
CH-5	CH-5	on.	blinking while alarm relay is		
A1S1	A 15 I	Alarm 1 set value of input channel 1			
A1S2	A 152	Alarm 1 set value of input channel 2			
A1S3	A 153	channel 3	Alarm 1 are for 5 input channels	-1999 — 9999	500
A1S4	A 154	Alarm 1 set value of input channel 4			
A1S5	A 155	Alarm 1 set value of input channel 5			
A2S1	A25 I	Alarm 2 set value of input channel 1			
A2S2	A252	Alarm 2 set value of input channel 2			
A2S3	A253	channel 3	Alarm 2 are for 5 input channels	-1999 — 9999	500
A2S4	A254	Alarm 2 set value of input channel 4			
A2S5	A255	Alarm 2 set value of input channel 5			
PVO1	Pºo I	Process value offset of input channel 1			
PVO2	PY-2	Process value offset of input channel 2	Process value offset, Use to offset the PV indication from the actual PV		
PVO3	PY-3	Process value offset of input channel 3			0
PVO4	PYa4	input channel 4			
PVO5	PY-5	Process value offset of input channel 5			

Ethno is set to 5.  SCA.T SCRE Scan rate for all channels.  Scan rate for all channels.  Set this to 0 if you do not wish it to scan automatically.  Description of the process value  Decimal point selection. (Linear input only) 0.01 and 0.001 resolution. After changing the decimal point, please reconfirm the parameter values below.  Lot Lot Lot Lot Low limit of span or range.  Lot Low limit of span or range.  Refer to Table 1  Low scale of linear input Lor High scale of linear input Lor High scale of linear input Lor Hysteresis for Alarm 1. While A1FU is set to T.on or T.off, the unit will be HHATO STASS.  A1FU RIPH Alarm 1 function. Used alone or with alarm mode. If A1FU = nonE, alarm function is cancelled.  A2FU RAPH Alarm 2 function. Used alone or with alarm mode. If A2FU = nonE, alarm function is cancelled.  A2FU RAPH Alarm 2 mode. Used with RIFU. If A1MD= nonE, alarm function is cancelled.  A2FU RAPH Alarm 2 mode. Used with RIFU. If A2MD= nonE, alarm mode is cancelled.  A2FU RAPH Time scale of timer alarm Addr RAPH RAPH RAPH RAPH Time scale of timer alarm Addr RAPH RAPH RAPH RAPH RAPH RAPH RAPH RAPH	_				I	
This is where you set the number of channels you channels are using. If 5 input channels are connected, 1-5  SCA.T SCAL SCAL SCAL SCAL SCAL SCAL SCAL SCAL	eter	Code	Description	Range		Default
CH.no  CH	tYPE	LYPE			o Table1	$\mathcal{L}$
SCA.T 5 FRE Scan rate for all channels.  Set this to 0 if you do not wish it to scan automatically.  Unit Unit Unit Unit Wheasuring unit of the process value  Decimal point selection. (Linear input only) 0.01 and 0.001 resolution. After changing the decimal point, please reconfirm the parameter values below.  LoLt LoLE Low limit of span or range.  HiLt HiLE High limit of span or range.  LoLL Low scale of linear input 1000 0.00 0.001 resolution 0.000 0.000 0.000 0.000 0.000 0.001 resolution 0.000 0.00	CH.no	Ен.по	are using. If 5 input channels are connected,	1~5		5
Decimal point selection. (Linear input only)  On and 0.001 resolution. After changing the decimal point, please reconfirm the parameter values below.  Lot Lot Lot Low limit of span or range.  Hilt Hilb Hilb High limit of span or range.  Loh Low scale of linear input  Loh Lot Lot High limit of span or range.  Refer to Table 1  On 1000  On 0.001 resolution  On 0.000  On 0.001 resolution  On 0.000 reso	SCA.T	SCRL	Scan rate for all channels.	Set this to 0 if you scan automatical	ou do not wish it to	0
Dp dP 0.01 and 0.001 resolution. After changing the decimal point, please reconfirm the parameter values below.  LoLt LaLE Low limit of span or range.  Hilt H IL High limit of span or range.  LoL Low limit of span or range.  Refer to Table 1 1000  LoL Low limit of span or range.  Refer to Table 1 1000  LoL Low scale of linear input 1000  Lol Low scale of linear input 1000  Lol Low limit of span or range.  Refer to Table 1 1000  Lol Low scale of linear input 1000  Lol Low limit of span or range.  Refer to Table 1 1000  Colo 0.001 resolution 0.000  0.001 resolution 0.000  0.001 resolution 0.000  Refer to Table 1 1000  Colo 0.001 resolution 0.000  Refer to Table 1 1000  Colo 0.001 resolution 0.000  Refer to Table 1 1000  Colo 0.001 resolution 0.000  Refer to Table 2 1000  Low scale of linear input 1000  Refer to Table 2 1000	Unit	Un iE	Measuring unit of the process value			°E
Hilt Hilt Hilt Hilt High limit of span or range.  Lour Lour Lour Lour Lour Lour Lour Lour	Dp		0.01 and 0.001 resolution. After changing the decimal point, please reconfirm the parameter	000.0	0.1 resolution 0.01 resolution	0000
LnLo LnLo LnLo Low scale of linear input LnHi LnHi LnHi High scale of linear input Hysteresis for Alarm 1. While A1FU is set to T.on or T.off, the unit will be HHoo or Journal of Journal of T.off, the unit will be HHoo or Journal of Journal o	LoLt	LoLE	Low limit of span or range. Refer to Table 1		0	
LnHi LnH i High scale of linear input  A1HY Hysteresis for Alarm 1. While A1FU is set to T.on or T.off, the unit will be HHor in it is set to T.on or T.off, the unit will be HHor in it is set to T.on or T.off, the unit will be HHor in it is set to T.on or T.off, the unit will be HHor in it is set to T.on or T.off, the unit will be HHor in it is set to T.on or T.off, the unit will be HHor in it is set to T.on or T.off, the unit will be HHor in it is set to T.on or T.off, the unit will be HHor in it is set to T.on or T.off, the unit will be HHor in it is set to T.on or T.off, the unit will be HHor in it is set to T.on or T.off, the unit will be HHor in it is set to T.on or T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in it is set to T.on on T.off, the unit will be HHor in T.off th	HiLt	HILE	High limit of span or range. Refer to Table 1		1000	
Hysteresis for Alarm 1. While A1FU is set to T.on or T.off, the unit will be HHōō 5055.  A2HY R2HY Hysteresis for Alarm 2. While A2FU is set to T.on or T.off, the unit will be HHōō 5055.  A1FU RIFU Alarm 1 function. Used alone or with alarm mode. If A1FU alarm 1 mode. Used with RIFU. If A1MD= Alarm 2 function. Used alone or with alarm mode. If A2FU alarm function is cancelled.  A2FU R2FU Alarm 2 function. Used alone or with alarm mode. If A2FU and E, alarm function is cancelled.  A2MD R2ōd Alarm 2 mode. Used with RIFU. If A2MD= Refer to Table 2  A2MD R2ōd Alarm 2 mode. Used with RIFU. If A2MD= Refer to Table 2  A2MD R2ōd Alarm 2 mode. Used with RIFU. If A2MD= Refer to Table 2  A2MD R2ōd Alarm 2 mode is cancelled.  A2MD R2ōd Communication address  A2MD R2ōd Communication address  A2MD R2ōd Communication baud rate  Communication baud rate  Communication baud rate  Communication baud rate	LnLo	LnLo	Low scale of linear input -1999~9999(-199.9~999.9)		0	
Hysteresis for Alarm 1. While A1FU is set to T.on or T.off, the unit will be HHōō \ \bar{no55}.  Hysteresis for Alarm 2. While A2FU is set to T.on or T.off, the unit will be HHōō \ \bar{no55}.  Hysteresis for Alarm 2. While A2FU is set to T.on or T.off, the unit will be HHōō \ \bar{no55}.  A1FU RIFU Alarm 1 function. Used alone or with alarm mode. If A1FU = nonE, alarm function is cancelled.  A1MD RIFU Alarm 1 mode. Used with RIFU. If A1MD= nonE, alarm mode is cancelled.  A2FU R2FU Alarm 2 function. Used alone or with alarm mode. If A2FU = nonE, alarm function is cancelled.  A2MD R2ōd Alarm 2 mode. Used with RIFU. If A2MD= nonE, alarm mode is cancelled.  A2MD R2ōd Alarm 2 mode. Used with RIFU. If A2MD= nonE, alarm mode is cancelled.  A2MD R2ōd Communication address  Addr R3dd R3dd R3dd R3dd P3dd Communication baud rate  Communication baud rate  Communication baud rate  D255 247	LnHi	LoHi			1000	
A1FU   If A1FU = nonE, alarm function is cancelled.  A1MD   R   Ind   Alarm 1 mode. Used with   R   IFU   If A1MD = nonE, alarm mode is cancelled.  A2FU   R2FU   Alarm 2 function. Used alone or with alarm mode. If A2FU = nonE, alarm function is cancelled.  A2MD   R2   Alarm 2 mode. Used with   R   IFU   If A2MD = nonE, alarm mode is cancelled.  A2MD   R2   Alarm 2 mode. Used with   R   IFU   If A2MD = nonE, alarm mode is cancelled.  A2MD   R2   Alarm 2 mode   If A2MD = nonE, alarm mode is cancelled.  A2MD   R2   Alarm 2 mode   If A2MD = nonE, alarm mode is cancelled.  A2MD   R2   Alarm 2 mode   If A2MD = nonE, alarm mode is cancelled.  A2MD   R2   Alarm 2 mode   If A2MD = nonE, alarm mode   If A2MD = nonE, alarm mode is cancelled.  A2MD   R2   Alarm 2 mode   If A2MD = nonE, alarm mode   I	A1HY A2HY	07111	or T.off, the unit will be HHAAA . AA55.  Hysteresis for Alarm 2. While A2FU is set to T.on	0~250 / 0.0~2 0.000	~0.250	1
ATMD H Ind nonE, alarm mode is cancelled.  A2FU R2FU If A2FU= nonE, alarm function is cancelled.  A2MD R2nd Alarm 2 mode. Used with R IFU. If A2MD= Refer to Table 2  PtmE PEnE Time scale of timer alarm  Addr R3485 communication address  BAUD R360 bps  BAUD R3600 bps	A1FU	A IFU		Refer to Table 2	Refer to Table 2	
A2FU R2FU   Alarm 2 function. Used alone of with alarm mode. If A2FU= nonE, alarm function is cancelled.  A2MD R2nd   Alarm 2 mode. Used with R IFU. If A2MD= nonE, alarm mode is cancelled.  PtmE   PEnE   Time scale of timer alarm   HHnn nonE   Addr   R3485 communication address   O~255   247    BAUD   BAUD   Communication baud rate   Communication baud r	A1MD	A Ind	nonE, alarm mode is cancelled.	Refer to Table 2		nonE
AZMD Hand nonE, alarm mode is cancelled.  PtmE Pane Time scale of timer alarm  Addr RS485 communication address  bAUd BAUd Communication baud rate  Refer to Table 2  HHan nonE  HHan nonE  1925  247  4800 bps  1924  19200 bps  1924  38400 bps	A2FU	02511	If A2FU= ¬¬¬¬E, alarm function is cancelled.	Refer to Table 2		Lo
Addr RS485 communication address 0~255 247  bAUd BRUd Communication baud rate 0~255 247  Communication baud rate 1920 bps 1924 38400 bps	A2MD	A2ād		Refer to Table 2		nonE
bAUd bBUd Communication baud rate    182   4800 bps   9600 bps   1924   19200 bps   1924   38400 bps   1924   1925	PtmE					
bAUd	Addr	Rddr	RS485 communication address	0~2	255	247
	bAUd	ЬЯИА	Communication baud rate	9.5 <i>L</i> 19.2 <i>L</i>	9600 bps 19200 bps	19.22
	LoCK	LaEY	Parameter lock			

#### 9. Alarm Functions:

In the parameter settings you first encounter the  $A \ IHU \ A2HU$  parameters. Hysteresis setting for alarms works with  $A \ IFU \ A2FU$  and sets a dead band below the alarm set point to avoid unnecessary tripping of the alarm.

The A IFU, A2FU settings are used to define how the alarms work. They can be used alone or in conjunction with the alarm mode parameters that dictate additional functions governing how the alarms function chosen will work. Alarm functions are as follows:

PonE: Alarm function is off. If the alarm function is set to ponE, alarm output is disabled.

H : Process high alarm. When PV≧ALSP, the alarm relay is ON. When PV < ALSP, the alarm relay is OFF.

- Lo: Process low alarm. When PV≦ALSP, the alarm relay is ON. When PV>ALSP, the alarm relay is OFF.
- E.on: On-timer alarm. When PV=SP, the alarm relay begins to count time and the alarm relay status LED A1 blinks. When the timers counts down to zero, the alarm relay is ON and the alarm relay status LED A1 lights.
- E.off: Off-timer alarm. On powering up the controller, the alarm relay will be ON and the alarm relay status LED lights up. When the PV=SP, the alarm relay begins to count the time and the alarm relay status LED A1 blinks. When the timer counts down to zero, the alarm relay will switch OFF and the alarm relay status LED A1 will be off.

Table 2

10010 =	Tuble 2				
A IFU A2FU	Code	Alarm output operation			
Alarm function off	nanE				
Process high alarm	Н	OFF ON PV			
Process low alarm	Lo	ON OFF PV ALSP			
On-timer	Ł.on	ON PV ALS1 ALS2 ON			
Off-timer	Ł.oFF	ON OFF  ALHY  ALS1 ALS2 OFF			

#### Alarm modes

The alarm mode functions  $\overrightarrow{A}$   $\overrightarrow{lnd}$ ,  $\overrightarrow{A}$   $\overrightarrow{cnd}$  are used with the alarm functions above and work as described in the table below.

Alarm mode Code		Description
	nonE	Disable the alarm mode
A 15d A25d	5EdY	Standby mode. When selected, in any alarm function, prevents an alarm on power up. The alarm is enabled only when the process value reaches set point. Also known as "Startup inhibit" and is useful for avoiding alarm trips during startup.
n ina Acha	LAEH	Latch mode. When selected, the alarm output and indicator latch as the alarm occurs. The alarm output and indicator will not change its state even if the alarm condition has been cleared unless the power is reset (off.
	SELB.	Both standby and Latch mode are applied.

### MODBUS RTU N,8,2

Read03/Write06		
0x0000	Туре	0:J 1:K 2:T 3:d-pt 4:Line
0x0001	Unit	0:°C 1:°F 2:ENG
0x0003		
0x0004		
0x0009	ChNo	1~5
0x000A	Scat	0~10
0x000B	Dp	Line(Type): 0~3 etc(Type): 0~1
0x000C	A1hy	none,Hi,Lo(A1fu): 0~250 etc(A1fu): 0~5999
0x000D	A2hy	none,Hi,Lo(A2fu): 0~250 etc(A2fu): 0~5999
0x000E	A1fu	0:none 1:Hi 2:Lo 3:ton 4:toff
0x000F	A1md	0:none 1:stdy 2:lath 3:st.la
0x0010	A2fu	O:none 1:Hi 2:Lo 3:ton 4:toff
0x0011	A2md	0:none 1:stdy 2:lath 3:st.la
0x0012	Ptme	0 : HH,MM 1 : MM,SS
0x0013	Lock	0~3 (Read Only)
0x0014	ID	1~255
0x0015	Baud	0:4.8K 1:9.6K 2:19.2K 3:38.4K
0x0016	A1s1	-1999~9999
0x0017	A1s2	-1999~9999
0x0018	A1s3	-1999~9999
0x0019	A1s4	-1999~9999
0x001A	A1s5	-1999~9999
0x001B	A2s1	-1999~9999
0x001C	A2s2	-1999~9999
0x001D	A2s3	-1999~9999
0x001E	A2s4	-1999~9999
0x001F	A2s5	-1999~9999
0x0020	Pvo1	Refer to Table1
0x0021	Pvo2	Refer to Table1
0x0022	Pvo3	Refer to Table1
0x0023	Pvo4	Refer to Table1
0x0024	Pvo5	Refer to Table1
Read04		
0x1000	Pv1	
0x1001	Pv2	
0x1002	Pv3	
0x1003	Pv4	
0x1004	Pv5	